



Обозначение	L, мм	Раб.t, °C	Рис.	d, мм	Кол-во рабочих спаев	Масса, кг
ТХА.ГПКШ.015	320	-40÷+1000	1	6,5	2	0,93
-01	320	-40÷+800	1	6,5	2	0,93
-02	400	-40÷+1000	1	6,5	2	1,00
-03	400	-40÷+800	1	6,5	2	1,00
-04	500	-40÷+1000	1	6,5	2	1,10
-05	630	-40÷+800	1	6,5	2	1,21
-06	800	-40÷+1000	3	6,5	2	1,28
-07	320	-40÷+1000	1	8	1	0,95
-08	320	-40÷+800	1	8	1	0,95
-09	400	-40÷+1000	1	8	1	1,03
-10	400	-40÷+800	1	8	1	1,03
-11	500	-40÷+1000	2	8	1	1,12
-12	630	-40÷+800	1	8	1	1,26
-13	800	-40÷+1000	3	8	1	1,33
-14	320	-40÷+1000	2	6,5	2	0,92
-15	320	-40÷+800	2	6,5	2	0,92
-16	400	-40÷+1000	2	6,5	2	1,00
-17	400	-40÷+800	2	6,5	2	1,00
-18	500	-40÷+1000	2	6,5	2	1,10
-19	630	-40÷+800	2	6,5	2	1,20
-20	320	-40÷+1000	2	8	1	0,94
-21	320	-40÷+800	2	8	1	0,94
-22	400	-40÷+1000	2	8	1	1,02
-23	400	-40÷+800	2	8	1	1,02
-24	500	-40÷+1000	2	8	1	1,12
-25	630	-40÷+800	2	8	1	1,25