




Схемы соединений



Обозначение	НСХ	L, мм	D, мм	d, мм	S, мм	Масса, г, не более
ТСМ.ГПКШ.037	50M	80	M20x1,5	10	22	200
- 01	50M	120	M20x1,5		22	210
- 02	50M	160	M20x1,5		22	215
- 03	50M	200	M20x1,5		22	230
- 04	50M	250	M20x1,5		22	240
- 05	50M	320	M20x1,5		22	240
- 06	50M	120	M27x2		30	270
- 07	50M	320	M27x2		30	200
- 08	50M	60	M20x1,5		22	190
- 10	100M	80	M20x1,5		22	210
- 11	100M	120	M20x1,5		22	215
- 12	100M	160	M20x1,5		22	220
- 13	100M	200	M20x1,5		22	215
- 14	100M	250	M20x1,5		22	220
- 15	100M	320	M20x1,5		22	230
- 16	100M	120	M27x2		30	240
- 17	100M	320	M27x2		30	270
- 21	50M	80	M20x1,5	9	22	200
- 22	50M	120	M20x1,5		22	210
- 23	50M	160	M20x1,5		22	215
- 24	50M	200	M20x1,5		22	230
- 25	50M	250	M20x1,5		22	240
- 26	50M	320	M20x1,5		22	240
- 27	50M	120	M27x2		30	270
- 28	50M	320	M27x2		30	200
- 31	100M	80	M20x1,5		22	210
- 32	100M	120	M20x1,5		22	215
- 33	100M	160	M20x1,5		22	220
- 34	100M	200	M20x1,5		22	215
- 35	100M	250	M20x1,5		22	220
- 36	100M	320	M20x1,5		22	230
- 37	100M	120	M27x2		30	240
- 38	100M	320	M27x2		30	270