



Обозначение	L, мм	Масса, г
ТХА.ГПКШ.017	10000	350
-01	20000	700
-02	35000	1230
-03	1200	45
-04	1500	55
-05	2000	70
-06	2500	90
-07	4000	140
-08	5000	180
-09	7000	245