

Рис.1




Рис. 2

Обозначение	Размеры попер. сеч., мм	d, мм	L, мм	Рис.	Масса, г, не более			
1	2	3	4	5	6			
ТХК.ГПКШ.013 - 35	D=6	1,08	50	1	9			
- 36			60		11			
- 37			80		14			
- 38			100		17			
- 39			120		21			
- 40			160		27			
- 41			200		34			
- 42			250		42			
- 43			320		53			
- 44			400		66			
- 45			500		83			
- 46			D=3		0,65	50		3
- 47						60		3
- 48	80	4						
- 49	100	5						
- 50	120	5						
- 51	160	7						
- 52	200	9						
- 53	250	11						
- 54	320	13						

- 55			400		17
- 56			500		21
- 57	BxH=2±3,5	0,7	80	2	4
- 58			100		4
- 59			120		5
- 60			160		6
- 61			200		7
- 62			250		8
- 63			320		10
- 64			400		12
- 65			500		14
- 66			630		17
- 67			800		22
- 68			1000		27
- 69	1200	32			